



BRITISH COLUMBIA

Ministry of Transportation and Infrastructure
Commercial Vehicle Inspection Report

FINAL INSPECTION CONFIRMATION NUMBER
9208248

EN 98901
EN98901

DECAL EXPIRY DATE
31 MAY 2014

INSPECTION RESULT: **Pass**
INSPECTION TYPE: **Complete**
REASON FOR INSPECTION: **Semi-Annual**
COLLISION REPAIR FACILITY:

WORK ORDER # **145891**
INSPECTION START DATE **14 NOV 2013 15:00**

INSPECTION COMPLETE DATE **14 NOV 2013 19:00**

REASON NOTE:
TECHNICIAN NAME:
PHONE #:

INSPECTOR'S NUMBER: **M10642**
INSPECTOR'S NAME: **CLEVERLEY, STUART DAVID**
LICENCE EXPIRY DATE: **30-APR-2015**
FACILITY NUMBER: **S3416**
FACILITY NAME: **IRL INTERNATIONAL TRUCK****
INSPECTION CLASS: **2 - Motor vehicle with lic. GVW of more than 5,500kgs**

OWNER/LESSEE: **HIGHLAND POWERLINES LTD**
ADDRESS: **969 CAMOSUN CRES**
CITY: **Kamloops** PROV: **BC** POSTAL CODE: **V2C6G1**
REGISTRATION #: **10638820** VEH. JURISDICTION: **BC** PLATE: **EL2334**
YEAR: **2004** MAKE: **INTERNATNA** MODEL:
BODY STYLE: **GIRAF** VIN: **1HTMMAAR94H655731**
ODOMETER: **9750 KM** FUEL TYPE: **Diesel**
UNIT/FLEET #: **215** BRAKE TYPE: **Air**

"F" Failed "R" Repaired Same Day "P" Passed "PC" Passed With Caution "O" Out Of Service "NA" Not Applicable

	F	R	P	PC	O	NA		F	R	P	PC	O	NA
Section 1 - Power Train			✓				Pressure Fuel						
							Liquid Propane Gas						✓
							Compressed Natural Gas						✓
Section 2 - Suspension			✓				Pressure Fuel Inspector's Name & Number						
Section 3 - Hydraulic Brakes					✓		Air Brake Chamber Type, Size and Push Rod Stroke Measurement (mm)						
Section 3A - Air Brakes			✓				Axle # 1 2 3 4 5 6 7 8 9						
Section 4 - Steering			✓				Type: Clamp Clamp						
Section 5 - Instruments, Auxillary Equipment			✓				Size: 20 30L						
Section 6 - Lamps			✓				Slack: Auto Auto						
Section 7 - Electrical System			✓				Left: 30 25						
Section 8 - Body & Frame			✓				Right: 30 25						
Section 9 - Tires & Wheels			✓				Comments:						
Section 10 - Couplers & Hitches					✓		Air Brake Camshaft Rotation Measurement (degrees)						
Section 10 - Special Use Vehicle Components							Axle # 1 2 3 4 5 6 7 8 9						
							Type: Lining (S Lining (S						
							Left: 17 19						
							Right: 17 19						
							Comments:						
							Brake Lining/Pad Measurement (mm)						
							Axle # 1 2 3 4 5 6 7 8 9						
							Type: Drum Drum						
							Left: 0 0						
							Right: 0 0						
							Comments: 1 - BACKPLATES REMOVED; 2 - BACKPLATES REMOVED						
General Inspection Comments:													

Inspector's Name **CLEVERLEY, STUART DAVID**

Signature

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement Branch, by writing to P.O. Box 9250, Stn Prov. Gov't, Victoria, BC V8W 9J2, by e-mailing to vehicle.inspections@gov.bc.ca or calling 250-952-0577.

CVSE0014 (100615)



BRITISH COLUMBIA

Ministry of Transportation and Infrastructure
Commercial Vehicle Inspection Report

FINAL INSPECTION CONFIRMATION NUMBER
9472616

EP
73962
EP73962

DECAL EXPIRY DATE
30 SEP 2014

INSPECTION RESULT: Pass
INSPECTION TYPE: Complete
REASON FOR INSPECTION: Semi-Annual
COLLISION REPAIR FACILITY:

WORK ORDER # 147403
INSPECTION START DATE 20 MAR 2014 16:00

INSPECTION COMPLETE DATE
20 MAR 2014 18:20

REASON NOTE:
TECHNICIAN NAME:
PHONE #:

INSPECTOR'S NUMBER: M08780
INSPECTOR'S NAME: SEREDIK, GORDON MICHAEL
LICENCE EXPIRY DATE: 31-JUL-2014
FACILITY NUMBER: S3416
FACILITY NAME: IRL INTERNATIONAL TRUCK**
INSPECTION CLASS: 2 - Motor vehicle with lic. GVW of more than 5,500kgs

OWNER/LESSEE: HIGHLAND POWERLINES LTD
ADDRESS: 969 CAMOUSUN CRES
CITY: Kamloops PROV: BC POSTAL CODE: V2C6G1
REGISTRATION #: 03949266 VEH. JURISDICTION: BC PLATE: BT4595
YEAR: 2003 MAKE: INTERNATNA MODEL:
BODY STYLE: GIRAF VIN: 1HTWGAAT83J053017
ODOMETER: 89290 KM FUEL TYPE: Diesel
UNIT/FLEET #: 212 BRAKE TYPE: Air

"F" Failed "R" Repaired Same Day "P" Passed "PC" Passed With Caution "O" Out Of Service "NA" Not Applicable

	F	R	P	PC	O	NA		F	R	P	PC	O	NA
Section 1 - Power Train			✓				Pressure Fuel						
							Liquid Propane Gas						✓
							Compressed Natural Gas						✓
Section 2 - Suspension			✓				Pressure Fuel Inspector's Name & Number						
Section 3 - Hydraulic Brakes						✓	Air Brake Chamber Type, Size and Push Rod Stroke Measurement (mm)						
Section 3A - Air Brakes			✓				Axle # 1 2 3 4 5 6 7 8 9						
REPAIR ABS LIGHT ON. RIGHT FRONT SENSOR							Type: Clamp Clamp Clamp						
Section 4 - Steering			✓				Size: 24L 30L 30L						
Section 5 - Instruments, Auxillary Equipment			✓				Stack: Auto Auto Auto						
Section 6 - Lamps			✓				Left: 32 37 38						
Section 7 - Electrical System			✓				Right: 32 38 38						
Section 8 - Body & Frame			✓				Comments:						
Section 9 - Tires & Wheels			✓				Air Brake Camshaft Rotation Measurement (degrees)						
Section 10 - Couplers & Hitches			✓				Axle # 1 2 3 4 5 6 7 8 9						
Section 11 - Other Vehicle Components			✓				Type: Lining (S Lining (S Lining (S						
							Left: 19 17 18						
							Right: 19 17 18						
							Comments:						
							Brake Lining/Pad Measurement (mm)						
							Axle # 1 2 3 4 5 6 7 8 9						
							Type: Drum Drum Drum						
							Left: 0 0 0						
							Right: 0 0 0						
							Comments: 1 - DRUMS NOT REMOVED; 2 - DRUMS NOT REMOVED; 3 - DRUMS NOT REMOVED						
Rotor/Drum Measurement (mm)													
Axle # 1 2 3 4 5 6 7 8 9													
Type: Drum Drum Drum													
Left: 0 0 0													
Right: 0 0 0													
Comments: 1 - DRUMS NOT REMOVED; 2 - DRUMS NOT REMOVED; 3 - DRUMS NOT REMOVED													

General Inspection Comments:

Inspector's Name SEREDIK, GORDON MICHAEL

Signature

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.
NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement Branch, by writing to P.O. Box 9250, Stn Prov. Gov't, Victoria, BC V8W 9J2, by e-mailing to vehicle.inspections@gov.bc.ca or calling 250-952-0577.



Lift Equipment, Inspections and Certifications

P.O. Box 3071
Kamloops, BC V2C 6B7Phone 250-374-7458
Fax 250-376-7479

Structural Inspection Certificate

Manufacturer	Altec
Model Number	A77-T
Serial Number	0702CT0467
Unit Number	132
Hour Meter Reading	4,704 hours
Odometer Reading	82,907 km
Reference Number	13-K3293
Date of Inspection	August 27, 2013
Certification Due Date	August 27, 2014

Visual and magnetic particle inspections were performed on the above-described 800 lb capacity manlift, owned by Highland Powerlines Ltd.

This manlift was non-destructively inspected, and where required, repaired and then re-examined. The specific components inspected were as follows:

1. Outriggers
2. Sub Frame
3. Main Frame
4. Turret
5. Lower Boom Section
6. FRP Boom Insulator
7. Upper Boom Extension
8. FRP Upper Boom Section
9. Manbasket Adaptor
10. FRP Manbasket

This structural inspection was performed on the equipment in the assembled condition. This certification is contingent on all previous structural repairs or modifications being performed in accordance with the original equipment manufacturers specifications or certification by a professional engineer.

Based on the results of the inspection and re-inspection of repairs where required, this equipment is considered to be suitable for continued service. In addition to this structural inspection, all applicable original equipment manufacturers specifications, CSA codes and OH&S regulations are to be followed. Any incident, deviation of normal operation or unauthorized structural repairs subsequent to this inspection will void the certification.

UNRAU TECHNOLOGIES LTD.
Inspector(s): Doug Besuyen CGSB Level II

A circular professional engineer's stamp for D.E. Richards, P.Eng., is overlaid with a handwritten signature. The stamp contains the text 'PROFESSIONAL ENGINEER', 'D.E. RICHARDS P.ENG.', and '2013'. The signature is written in cursive over the stamp.

The above information was reviewed by:
D.E. Richards P.Eng.
Per: RED ASSOCIATES ENGINEERING LTD

P.O. Box 3071 Kamloops, BC V2C 6B7 PH: (250) 374-7458 Fax: (250) 376-7479